

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Reference Fig1

Surface of diamond
after inclined po-
lishing



(a)

Surface of diamond
after exposing to
H₂ plasma for 30
minutes





(b)

microwave power:500W, substrate temperature:830° C





Surface of diamond
after exposing
H₂ plasma for 60
minutes



Height histogram
of surface

Surface of diamond
after exposing
H₂ plasma for 120
minutes



Height histogram
of surface